


RELATED ART
Fig. 1A

RELATED ART
Fig. 1B



RELATED ART
Fig. 2A

RELATED ART
Fig. 2B





Fig. 3

*Fig. 4*

5/14




Fig. 5

6/14




Fig. 6

7/14




Fig. 7

8/14




Fig. 8

9/14




Fig. 9

		DENSITY OF POROUS GLASS SOOT (g/cm ³)	FLUORINE GAS CONTENT (Vol%)	SINTERING SPEED (mm/min)	QUALITY OF REFRACTIVE INDEX PROFILE
EXAMPLE	1	0.22	2	7.0	GOOD
	2	0.22	6	7.0	GOOD
COMPARATIVE EXAMPLE	1	0.42	100	4.0	COULD NOT MANUFACTURE CORE
	2	0.20	35	7.0	BAD
	3	0.22	2	1.0	BAD
	4	0.22	6	1.0	BAD
	5	0.22	1.6	3.0	BAD
	6	0.22	2	3.0	BAD
	7	0.22	6	3.0	BAD

Fig. 10

11/14




Fig. 11

12/14




Fig. 12

13/14




Fig. 13




Fig. 14




Fig. 14